



Certificate of Registration

QUALITY MANAGEMENT SYSTEM - EN 9100:2018

This is to certify that: Component Coating & Repair Services Ltd

Block 8 Unit 12/13

Thornliebank Industrial Estate

Glasgow G46 8JQ

United Kingdom

Holds Certificate Number: FS 32843

and operates a Quality Management System, with a Single site certification structure, which complies with the requirements of EN 9100:2018 (technically equivalent to AS9100D and JISQ 9100:2016) and ISO 9001:2015 and is assessed in accordance with EN 9104-001:2013 for the following scope:

The coating and non-destructive testing by the FPI method of gas turbine components for the Aviation and Industrial sectors of Industry.

For and on behalf of BSI:

Andrew Launn, EMEA Systems Certification Director

Original Registration Date: 2005-06-02

Reissue Date: 2020-01-28

Issue Date: 2020-01-28 Expiry Date: 2023-01-27

Page: 1 of 1

bsi.





aerospace sector certification scheme

...making excellence a habit."

This certificate was issued electronically and remains the property of BSI and is bound by the conditions of contract. An electronic certificate can be authenticated <u>online</u>. Printed copies can be validated at www.bsigroup.com/ClientDirectory