

Certificate of Registration

QUALITY MANAGEMENT SYSTEM - EN 9100:2018

This is to certify that:

Component Coating & Repair Services Ltd
Block 8
Unit 12/13
Thornliebank Industrial Estate
Glasgow
G46 8JQ
United Kingdom

Holds Certificate Number:

FS 32843

and operates a Quality Management System, with a Single site certification structure, which complies with the requirements of EN 9100:2018 (technically equivalent to AS9100D and JISQ 9100:2016) and ISO 9001:2015 and is assessed in accordance with EN 9104-001:2013 for the following scope:

The coating and non-destructive testing by the FPI method of gas turbine components for the Aviation and Industrial sectors of Industry.

For and on behalf of BSI:

Andrew Launn, EMEA Systems Certification Director

Original Registration Date: 2005-06-02

Reissue Date: 2018-09-07

Issue Date: 2017-01-28

Expiry Date: 2020-01-27



aerospace
sector
certification
scheme

Page: 1 of 1

...making excellence a habit.™