





## Certificate of Registration

## QUALITY MANAGEMENT SYSTEM - EN 9100:2018 AND ISO 9001:2015

This is to certify that:

Component Coating & Repair Services Ltd Block 8 Unit 12/13 Thornliebank Industrial Estate Glasgow G46 8JQ United Kingdom

Holds Certificate Number:

FS 32843

and operates a Quality Management System, which complies with the requirements of EN 9100:2018 (technically equivalent to AS9100D and JISQ 9100:2016) and ISO 9001:2015 and is assessed in accordance with EN 9104-001:2013 for the following scope:

The coating and non-destructive testing by the FPI method of gas turbine components for the Aviation and Industrial sectors of Industry.

For and on behalf of BSI:

Matt Page, Managing Director Assurance - UK & Ireland

Original Registration Date: 2005-06-02 Reissue Date: 2023-01-28



Issue Date: 2023-01-28 Expiry Date: 2026-01-27

Page: 1 of 1

...making excellence a habit."

This certificate was issued electronically and remains the property of BSI and is bound by the conditions of contract. An electronic certificate can be authenticated <u>online</u>. Printed copies can be validated at www.bsigroup.com/ClientDirectory

Information and Contact: BSI, Kitemark Court, Davy Avenue, Knowlhill, Milton Keynes MK5 8PP. Tel: + 44 345 080 9000 BSI Assurance UK Limited, registered in England under number 7805321 at 389 Chiswick High Road, London W4 4AL, UK. A Member of the BSI Group of Companies.